

Basic Vehicle Condition Guide

Report ID: 17,490,944


Version: 2

Created: 01 Dec 2018

Make: Model: Holden Cruze **Body Style:** Sedan Year: 2016 Registration: **KCU380** Reg Expiry: 01 May 2018 WoF Expiry: **Odometer: Good No:** 17490944 30 Nov 2019 39,431 Kms VIN: 6G1PE5EM3GL246490 Next Service: 45000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | | |
|-------------------|------|--|--|--|--|
| Seats | Good | | | | |
| Carpets | Good | | | | |
| Panels | Good | | | | |
| Dashboard | Good | | | | |

General Comments

Cambelt due at 150000kms

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

I have read and understood this condition guide.

Evidence of Cam Belt Replacement: Not Applicable Kms:

Chris Buckley Inspected by:

Name:

| | | Pass | Fail | N/A | | | |
|---------------|------------------------------|--|------|-----|--|--|--|
| | Engine | | | | | | |
| | Oil level | ~ | | | | | |
| | Smoke & fumes | ~ | | | | | |
| 1 | Performance | \(\triangle \) | | | | | |
| | Noise | ~ | | | | | |
| | Cooling System | | | | | | |
| | Coolant condition | ~ | | | | | |
| | Performance | ~ | | | | | |
| | Radiator / Hoses (visual) | ~ | | | | | |
| | Transmission | | | | | | |
| | Operation | ~ | | | | | |
| | Noise | V | | | | | |
| J | Clutch | | | ~ | | | |
| | CV joints | ~ | | | | | |
|] | Wheel bearings | ~ | | | | | |
| | Brakes | | | | | | |
| | Performance | ~ | | | | | |
| | Hand Brake | ~ | | | | | |
| | Tyres (lowest observed tread | Tyres (lowest observed tread depth of tyres) | | | | | |
| | Left front | 7 | .0 | mm | | | |
| | Right front | 7 | .0 | mm | | | |
| | Left rear | 6 | .0 | mm | | | |
| | Right rear | 6.0 | | mm | | | |
| _ | Spare | | Yes | | | | |
| | Suspension | | | | | | |
| | Suspension performance | ~ | | | | | |
| | Steering performance | <i>v</i> | | | | | |
| | Shock absorbers | ~ | | | | | |
| | Air Conditioning / Heater | | | | | | |
| 7 | Operation | ~ | | | | | |
| | Electrical / Accessories | | | | | | |
| | Head lights | ~ | | | | | |
| | Tail lights | ~ | | | | | |
| | Indicators | V | | | | | |
| | Dashboard warning lights | V | | | | | |
| | Wipers (front & rear) | • | | | | | |
| | Window winder FL | ~ | | | | | |
| _ | Window winder FR | ~ | | | | | |
| | Window winder RL | ~ | | | | | |
| | Window winder RR | ~ | | | | | |
| | Rear view mirrors | ~ | | | | | |
| | Radio (basic test only) | ~ | | | | | |
| | CD (basic test only) | ~ | | | | | |
| | Number of keys | 2 | | | | | |
| | Central locking | ~ | | | | | |
| ⊥ ¬ | Remote locking | ~ | | | | | |
| | Sat. Nav. (basic test only) | | | ~ | | | |
| | Reversing camera | | | ~ | | | |
| _ | | 10 | | | | | |
| | Date: 30 Oct 2018 | | | | | | |

Signature: