

Report ID: 17,491,181 Version: 1 Created: 09 Oct 2018

Make:	Holden	Model:	Cruze	Body Style:	Sedan		Pass	Fail	N/A
Year:	2016	Registration:	KDA791	Reg Expiry:	01 May 2018	Engine	1		I
WoF Expiry:	-	Odometer:	145,146 Kms	Good No:	17491181	Oil level	~		
VIN:	6G1PE5EM7GL246511	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	untina in mode	for any and miles as	Danta hava nat	heen dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC D D D D D D D D D D D D D D D D D D						Operation	~		
R = rust PT = paint defe				\prod		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	~		-
* = decals	sc 916			-NG		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Body Incr	naction Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
					Left front 6 m			mm	
						Right front	6		mm
						Left rear	8		mm
Conditions During Body Inspection: Dry						Right rear	8		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		
Incracto	d by: Stuart Melbourr					Date: 09 Oct 20	18		
Inspected by: Stuart Melbourne Date: 09 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: