

Report ID: 17,491,390


Version:

03 Sep 2018 Created:

| Make: | Holden | Model: | Captiva 7 | Body Style: | SUV |
|-------------|-------------------|---------------|------------|-----------------|-------------|
| Year: | 2,017 | Registration: | KHL504 | Reg Expiry: | 01 May 2018 |
| WoF Expiry: | | Odometer: | 43,235 Kms | Good No: | 17491390 |
| VIN: | KL3CD2659GB538305 | Next Service: | Unknown | Service History | /: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | | |
|-------------------|------|--|--|--|--|
| Seats | Good | | | | |
| Carpets | Good | | | | |
| Panels | Good | | | | |
| Dashboard | Good | | | | |

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Date: 03 Sep 2018 Inspected by: Murray Craig

| | Pass | Fail | N/A |
|------------------------------|---------------------------------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | V V | | |
| Performance | ~ | | |
| Noise | > | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | <i>V V</i> | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | | • |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | / | | |
| Tyres (lowest observed tread | depth | of tyre | es) |
| Left front | 4 | 1 | mm |
| Right front | *** | 3 | mm |
| Left rear | 1 | 5 | mm |
| Right rear | | 5 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ' | | |
| Tail lights | ~ | | |
| Indicators | ' | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | V V V V V V V V V V V V V V V V V V V | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | | | ~ |
| Number of keys | 2 | | 1 |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | ~ | | |
| | | | |

I have read and understood this condition guide.

Name:

Signature: