

Report ID: 17,491,825 Version: 1 Created: 19 Apr 2018

Make:	Mercedes-Benz	Model:	C200	Body Style:	Sedan		Pass	Fail	N/A
Year:	1,997	<b>Registration:</b>	DNC701	<b>Reg Expiry:</b>	19 Jul 2018	Engine	1	I	
WoF Expiry:	07 Oct 2018	Odometer:	151,534 Kms	Good No:	17491825	Oil level	~		
VIN:	WDB2020202F587467	Next Service:	149552	Service Histor	<b>y:</b> No	Smoke & fumes	V		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise		r	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			1
D = dent R = rust	w dla			ZIS	HIL	Operation	~		
PT = paint defe				$\left[ \right] \left[ \right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HID				ᅰᇉ	CV joints			~
* = decals	DSC 916			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W D						Performance	~		
Redu Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
Stone chips front screen. Left front door glass not working. Centre console lid trim worn.								mm	
						Right front		2	mm
						Left rear		3	mm
Conditions During Body Inspection: Wet						Right rear		3	mm
Conditions During Body Inspection: Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Slight oil lea	ak.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL		~	
	I					Window winder FR	~		
General Comments						Window winder RL	~		
Noise in engine pulley area. Tidy and runs well.						Window winder RR	~		
						Rear view mirrors	V		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2	I	1
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
L							1	1	I
Inspected by: Brian Hill Date: 19 Apr 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....