

Report ID: 17,644,609 Version: 1 09 Nov 2018 Created:

Make:	Toyota	Model:	Hiace	Body Style:	Van		Pass	Fail	N/A
Year:	2014	Registration:	HSE78	Reg Expiry:	29 Jan 2019	Engine	1		
WoF Expiry:		Odometer:	213,163 Kms	Good No:	17644609	Oil level	×		
VIN:	JTFHT02P300147814	Next Service:		Service History		Smoke & fumes	×		
			21.000			Performance	×		
	port is not a warranty					Noise	×		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	×		
Key:		-0	IS IS		Р	Radiator / Hoses (visual)	×		
S = scratch						Transmission			
						Operation X			
						Noise			
PT = paint defe C = crack	ect			$\square$	SC	Clutch	×		
P = pin dent	H	KI				CV joints			× ×
* = decals	sc pp			SIL.	FILE T	Wheel bearings			*
SC = stone chips						<b>_</b>			
W = significant scuffs W P S D W S						Brakes			
						Performance	×		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	×		
L side windows damaged					Tyres (lowest observed tread				
						Left front		5	mm
						Right front	4	1	mm
						Left rear	6 mm		mm
Conditions During Body Inspection: Wet						Right rear	6 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy						Suspension performance	×		
						Steering performance	×		
Shock							×		
						Air Conditioning / Heater			
						Operation X			
Interior Comments						Electrical / Accessories			
Seats	RF hole					Head lights	×		
Correcto	Average					Tail lights	×		
Carpets						Indicators	×		
Panels	Average					Dashboard warning lights	×		
	, Good					Wipers (front & rear)	×		
Dashboa	ra					Window winder FL	×		
						Window winder FR	×		
General C	<u>Comments</u>					Window winder RL			×
						Window winder RR			×
						Rear view mirrors	×		
						Radio (basic test only)	×		
						CD (basic test only)	×		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	×		
			vvcl			Remote locking	×		
Engine Tir	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			×
Evidence of Cam Belt Replacement: Yes Kms: 152,660						Reversing camera			×
	-					-			
Inspected by: Stuart Melbourne Date: 09 Nov 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....