

Basic Vehicle Condition Guide

Report ID: 17,644,943


Version: 1

Created: 08 Nov 2018

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2013 Registration: **GWT180** Reg Expiry: 27 Jul 2019 Good No: WoF Expiry: **Odometer:** 22 Jun 2019 158,939 Kms 17644943 VIN: KMHST81BSDU15835: Next Service: 163000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Stone chips front screen. Lower front bumper valance broken. Towbar coupling in boot. No cargo blind.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

			1	
	Pass	Fail	N/A	
Engine		1	1	
Oil level	×			
Smoke & fumes	X			
Performance	×			
Noise	×			
Cooling System		1	1	
Coolant condition	×			
Performance	×			
Radiator / Hoses (visual)	×			
Transmission				
Operation	×			
Noise	×			
Clutch			×	
CV joints	×			
Wheel bearings	×			
Brakes			•	
Performance	×			
Hand Brake	×			
Tyres (lowest observed treac	depth	of tyre	es)	
Left front 2 mm				
Right front	3		mm	
Left rear	3		mm	
Right rear	5		mm	
Spare		Yes		
Suspension				
Suspension performance	×			
Steering performance	×			
Shock absorbers	×			
Air Conditioning / Heater			1	
Operation	×			
Electrical / Accessories			1	
Head lights	×			
Tail lights	×			
Indicators	×			
Dashboard warning lights	×			
Wipers (front & rear)	×			
Window winder FL	×			
Window winder FR	×			
Window winder RL	×			
Window winder RR	×			
Rear view mirrors	×			
Radio (basic test only)	×			
CD (basic test only)	×			
Number of keys	2		<u> </u>	
Central locking	X			
	<u> </u>			
	X			
Remote locking	×		x	
	×		x	

I have read and understood this condition guide.

Name:

Signature:

08 Nov 2018

Date: