

Report ID: 17,646,257 Version: 1 21 Nov 2018 Created:

Make:	Volkswagen	Model:	Polo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	Registration:	JAE551	Reg Expiry:	08 Mar 2019	Engine	I	<u> </u>	L
WoF Expiry:		Odometer:	122,731 Kms	Good No:	17646257	Oil level	~		
VIN:	WVWZZZ9NZ6Y13866	Next Service:	122000	Service Histor	y: No	Smoke & fumes	~		
						Performance	r		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
	SC W		S S			Performance	~		
Key:				500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				210	EIII PT	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc				7411 <u>6</u>	CV joints	~		
* = decals		10		10	E S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
- Significan	SC C	w	SC		SC	Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Stone chips front screen.						Tyres (lowest observed tread depth of tyres)			es)
						Left front 3			mm
						Right front	4	1	mm
						Left rear	7	7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Compete	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ira 5ª					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement:YesKms:201,628						Reversing camera			~
·									
Inspected by: Brian Hill Date: 21 Nov 2018									

I have read and understood this condition guide.

Name:

Signature: