

Report ID: 17,646,652 Version: 1 03 Dec 2018 Created:

Make:	Hyundai	Model:	lload	Body Style:	Van		Pass	Fail	N/A
Year:	2013	Registration:	HCY656	Reg Expiry:	29 Jan 2019	Engine	I		L
WoF Expiry:	31 Oct 2019	Odometer:	128,770 Kms	Good No:	17646652	Oil level	~		
VIN:	KMFWBX7KMDU5875	Next Service:	135,000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for and milaan	Darte have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	SC W	-0	SP SW	-01-	W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent						Operation	~		
R = rust PT = paint def				\prod	JUIL	Noise	~		
C = crack				+	D	Clutch	-		~
P = pin dent					세비	CV joints			~
* = decals	sc 916			-No-		Wheel bearings	~		
SC = stone chips						Brakes	es		
W = significan	t scuffs D		P			Performance	~		
Darkulara		Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	-	of tyre	L 25)
Stone chips to f/screen						Left front			
						Right front	6		mm
						Left rear	5		mm
Conditions During Body Inspection: Wet						Right rear			mm
Conditions During Body Inspection: Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Drivers sea	at worn				Head lights	~		
	Pubborm	ats / hole in drive	arc footwall			Tail lights	~		
Carpets	Nubberina		is lootwell			Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		<u> </u>
Dashboa	ird					Window winder FL	~		<u> </u>
	1				J	Window winder FR	~		
General Comments						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspecte	d by: Murray Craig					Date: 03 Dec 20			
Inspected by, Manay Claig Date, 05 Dec 2010									

I have read and understood this condition guide.

Name:

Signature: