

Report ID: 17,647,040 Version: 4 14 Jan 2019 Created:

Make:	Holden	Model:	Adventra	Body Style:	SUV		Pass	Fail	N/A	
Year:	2005	Registration:	CWP887	Reg Expiry:	25 May 2019	Engine				
WoF Expiry:	26 Dec 2019	Odometer:	191,160 Kms	Good No:	17647040	Oil level	~			
VIN:	6G1ZM847X5L458633	Next Service:	190000	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
	SC W					Performance	~			
Key:	SC W	-0		-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent R = rust W D D W W						Operation	~			
PT = paint defe		F		$\left[\left(\right) \right]$		Noise	~			
C = crack				$+ \mathbf{\nabla}$	D	Clutch			~	
P = pin dent	HID				세비	CV joints	~			
* = decals	sc 916			- No	ALD S	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S W W						Performance	~			
Dealerteen		Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~			
1 .	bection Comments				, ,	Tyres (lowest observed treat	d depth	oftvre	es)	
No cargo blind. Left rear door glass not working. Right mirror housing broken						Left front 4.0 mm				
						Right front		.0	mm	
						Left rear	4.0		mm	
Conditions During Rody Inspection: Wat						Right rear	4.0		mm	
Conditions During Body Inspection: Wet						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
minor oil le	-	•				Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	v			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats Poor						Head lights	~			
						Tail lights	~			
Carpets	Average						~ ~			
Dem -1-	Average					Dashboard warning lights	v v			
Panels						Wipers (front & rear)	<i>v</i> <i>v</i>			
Dashboa	rd Average					Window winder FL	<i>v</i> <i>v</i>			
						Window winder FL	<i>v</i> <i>v</i>			
General (<u>Comments</u>					Window winder RL	~			
Brake pedal little spongy.						Window winder RL	~	~		
						Rear view mirrors	~			
						Radio (basic test only)	v v			
						CD (basic test only)				
						Number of keys	2			
						• · · · · · · · · · · · · · · · · · · ·	2			
Road Con	ditions During Test	Drive:	Wet			Central locking	v			
Engine Ti	ming Mechanism:	Timing	Chain			Remote locking Sat. Nav. (basic test only)	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:									v	
						Reversing camera			~	
Inspected by: Brian Hill Date: 27 Nov 2018										

I have read and understood this condition guide.

Name:

Signature: