

## **Basic Vehicle Condition Guide**

Report ID: 17,648,863


Version: 1

Created: 05 Dec 2018

Make: Model: Ford Mondeo **Body Style:** Wagon Year: 2007 Registration: DSY417 Reg Expiry: 10 Jul 2019 WoF Expiry: **Odometer: Good No:** 24 Feb 2019 282,298 Kms 17648863 VIN: WF0WXXGBBW6B816 Next Service: 288481 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Stone chips front screen

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments				
Seats	Poor			
Carpets	Average			
Panels	Good			
Dashboard	Good			

## **General Comments**

Noise in engine pulley area.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Brian Hill Date: 05 Dec 2018

		1	
	Pass	Fail	N/A
Engine			1
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise		~	
Cooling System		1	1
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission		1	
Operation	~		
Noise	~		
Clutch	\( \times \)		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	3		mm
Right front	5		mm
Left rear	:	3	
Right rear	6		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	1		ı
Operation		~	
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\( \times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	V V V		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	V		
CD (basic test only)	~		
Number of keys	1		
Central locking	·		
Remote locking	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Sat. Nav. (basic test only)	+		1
Reversing camera			./
eversing currieta			

I have read and understood this condition guide.

Name: .....

Signature: .....