

Report ID: 17,648,918 Version: 3 08 Feb 2019 Created:

Make:	Nissan	Model:	Primera	Body Style:	Sedan		Pass	Fail	N/A
Year:	2001	Registration:	FPF76	Reg Expiry:	19 Jul 2019	Engine		1	
WoF Expiry:	19 Feb 2020	Odometer:	136,981 Kms	Good No:	17648918	Oil level	~		
VIN:	7AT0DH2GX10014370	Next Service:	147000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and tl	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
	C.W.					Performance	~		
Key:	SW	-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	DW			715	HILD	Operation	~		
PT = paint defe				$\left[\left(\right) \right]$		Noise	~		
C = crack					S P	Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	sc 916			The second	AD P	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC W W						Performance	~		
Deduction		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
1	pection Comments					Tyres (lowest observed tread	d depth	of tyre	2s)
Stone chips front screen. Dent left cant rail. Rear ashtray missing. Heater fan is noisy.									mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear		.0	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension		103	
	-	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation			
Interior Comments						Electrical / Accessories	•		
Good Good						Head lights	~		
						Tail lights	~		
Carpets	Good						~		
Panels	Good					Dashboard warning lights	~		
Pariels						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	v v		
						Window winder FR	<i>v</i> <i>v</i>		
General Comments						Window winder RL	~		
minor suspension noise ok for age/kms						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	-	~	
						Number of keys	2	•	L
Pood Conditions During Tost Driver						Central locking	2 1		
Road Conditions During Test Drive: Dry						Remote locking	<i>v</i> <i>v</i>		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			<i>v</i> <i>v</i>
Inspected by: Brian Hill Date: 06 Dec 2018									

I have read and understood this condition guide.

Name:

Signature: