

Basic Vehicle Condition Guide

Report ID: 17,651,089


Version: 2

Created: 26 Feb 2019

Make: Model: Holden Colorado 7 **Body Style:** SUV Year: 2015 Registration: JFY539 Reg Expiry: 28 Apr 2019 WoF Expiry: **Odometer: Good No:** 20 Aug 2019 114,313 Kms 17651089 VIN: MMU156MK0GH6045 Next Service: 120,000kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips on screen .

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

OK.

Interior Comments		
Seats	Good	
Carpets	Average	
Panels	Good	
Dashboard	Good	

General Comments

Good AWD 7 seater SUV.

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Daryll Timms

Evidence of Cam Belt Replacement: No Kms:

Date: 27 Dec 2018

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\triangle \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	es)
Left front	4	.0	mm
Right front	5.0		mm
Left rear	4.0		mm
Right rear	3.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance		~	
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights			
Indicators	~		
Dashboard warning lights	\(\triangle \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	_		
Williadw Williael I IX	~		
Window winder RL	V		
	> >		
Window winder RL	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Window winder RL Window winder RR Rear view mirrors	> > > > > > > > > > > > > > > > > > >		
Window winder RL Window winder RR Rear view mirrors Radio (basic test only)	~		
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	\(\times \)		~
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	1		V
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	\(\times \)		V
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking Remote locking	1		V
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	1		V

I have read and understood this condition guide.

Name:

Signature: