

Turners Certified Imports 50 Point Check

Report ID: 17,651,321 Version: 1 09 Jan 2019 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Nissan	Body Style:	Hatchback
Model:	March	Odometer:	19,317 Kms
Year:	2010	VIN:	7AT0DH0KX18521991

Under Carriage & Under Bonnet Inspection Comments Tidy.

General Comments

Nice tidy, low km hatch.

Seats:	Good		
Seats			
Carpets:	Good		
Panels:	Good		
	Good		
Dashboard:	0000		
Engino Timi	ng Mechanism:	Timing Chain	
	ig mechanism.	-	
Evidence of	Cam Belt Benlacement:	Not Applicable	

Dry

Evidence of Cam Belt Replacement:

Replaced At (odometer reading):

Road Conditions During Test Drive:

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)	
Battery	Operation 🖌	Oil level	Left front 5 mm	
Head lights	Noise	Smoke & fumes	Right front 5 mm	
Tail lights	Clutch	Performance	Left rear 5 mm	
Indicators	CV joints	Noise	Right rear 5 mm	
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes	
Wipers (front & rear)	Wheel balance	Coolant condition	Tools	
Window winder FL	Brakes	Performance	Interior	
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation	
Window winder RL	Hand Brake		Heater fan	
Window winder RR		Suspension	Seatbelts	
Rear view mirrors	Keys & Locking	Suspension performance	Horn	
Radio (basic test only)	Central locking	Steering performance		
CD (basic test only)	Remote locking •	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle	
Reversing camera	Number of keys 1	Inspected by: Daryll Timms	Date: 09 Jan 2019	

Signature: