



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	17,651,473
Version:	2
Created:	20 Jun 2019

Make:	Subaru	Body Style:	Wagon
Model:	Legacy	VIN:	7AT0GF0BX18008377
Year:	2009	Odometer:	102,460 Kms
Road Conditions During Test Drive:	Dry		

Electrical			30	Fuel Flap Release	✓	Cooling System			78	Under Carriage	Good	Exterior		
1	Battery	✓	31	Reversing Camera	✓	55	Coolant Condition	✓	79	Sun Roof Operation	<input type="checkbox"/>	<div>Turners Certification Key: ✓ = Pass ✗ = Fail • = Not applicable for this vehicle</div>		
2	Headlights	✓	32	USB Port	<input type="checkbox"/>	56	Performance	✓	80	Front Windscreen (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	<input type="checkbox"/>	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good			
4	High Stop Light	<input type="checkbox"/>	Transmission and Drive			Suspension			82	Side Windows (no chips)	Good			
5	Front Right Indicators	✓	34	Operation	✓	58	Suspension Performance	✓	83	Front Wiper Blades	Good			
6	Front Left Indicators	✓	35	Noise	✓	59	Steering Performance	✓	84	Rear Wiper Blade	Good			
7	Rear Right Indicators	✓	36	Clutch	•	60	Shock Absorbers	✓	85	R/H Mirror	Good			
8	Rear Left Indicators	✓	37	CV Joints	✓	Wheels and Tyres			86	L/H Mirror	Good			
9	Reversing Lights	<input type="checkbox"/>	38	Wheel Bearing	✓	61	Left Front	6.0	87	L/F Guard	Good			
10	Rear Reflectors	<input type="checkbox"/>	39	Wheel Balance	✓	62	Right Front	6.0	88	R/F Guard	Good			
11	Hazard Lights	<input type="checkbox"/>	40	Gearbox (Manual)	<input type="checkbox"/>	63	Left Rear	4.0	89	L/H Doors	Good			
12	Courtesy Lights	<input type="checkbox"/>	41	Engine Timing	Cambelt	64	Right Rear	4.0	90	R/H Doors	Good			
13	Dashboard Lights	<input type="checkbox"/>	42	Evidence of Cam Belt Replacement	Yes	65	Spare	Yes	91	L/H Sill	Good			
14	Dashboard Dimmer Switch	<input type="checkbox"/>	43	Replaced at (odometer reading)	0	66	Tools	✓	92	R/H Sill	Good			
15	Number Plate Light	<input type="checkbox"/>	Brakes			Interior			93	Boot/Tail Gate	Good			
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	67	AC Operation	✓	94	Front Bumper	Good			
17	Speedo	<input type="checkbox"/>	45	Rear Brakes	✓	68	Heater Fan	✓	95	Rear Bumper	Good			
18	Odometer	<input type="checkbox"/>	46	Handbrake	✓	69	Seatbelts	✓	96	Roof	Good			
19	Rev Counter	<input type="checkbox"/>	Keys and Locking			70	Horn	✓	97	Bonnet	Good			
20	Fuel Gauge	<input type="checkbox"/>	47	Central Locking	✓	71	Seat Heaters	<input type="checkbox"/>	98	Fuel Cap	✓			
21	Wipers Front/Rear	✓	48	Remote Locking	✓	72	Sun Visors	✓	99	Mud Flaps	✓			
22	Window Opener FL	✓	49	Number of Keys	2	73	Sun Visors Lights/Mirrors	✓	100	WOF	✓			
23	Window Opener FR	✓	Engine			74	Seats	Good						
24	Window Opener RL	✓	50	Oil Level	✓	75	Carpets	Good						
25	Window Opener RR	✓	51	Smokes and Fumes	✓	76	Panels	Good						
26	Rear View Mirrors	✓	52	Performance	✓	77	Dashboard	Good						
27	Radio (Basic Test Only)	✓	53	Noise	✓									
28	CD (Basic Test Only)	✓	54	Starter Motor	✓									
29	Boot Open Switch	✓												