# Turners Certified Imports 50 Point Check

Report ID: 17,651,537
Version: 1
Created: 07 Jan 2019

**Note: This report is not a warranty**
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

| | | | |
|---|---|---|---|
| Make: | Toyota | Body Style: | Hatchback |
| Model: | Passo | Odometer: | 35,188 Kms |
| Year: | 2012 | VIN: | 7AT0H650X18019198 |

| | |
|---|---|
| Seats: | Good |
| Carpets: | Good |
| Panels: | Good |
| Dashboard: | Good |

**Under Carriage & Under Bonnet Inspection Comments**
Tidy .

**General Comments**
Nice funky little hatch .

| | |
|---|---|
| Engine Timing Mechanism: | Timing Chain |
| Evidence of Cam Belt Replacement: | Not Applicable |
| Replaced At (odometer reading): | |
| Road Conditions During Test Drive: | Dry |

## Electrical

| | |
|---|---|
| Battery | ✔ |
| Head lights | ✔ |
| Tail lights | ✔ |
| Indicators | ✔ |
| Dashboard warning lights | ✔ |
| Wipers (front & rear) | ✔ |
| Window winder FL | ✔ |
| Window winder FR | ✔ |
| Window winder RL | ✔ |
| Window winder RR | ✔ |
| Rear view mirrors | ✔ |
| Radio (basic test only) | ✔ |
| CD (basic test only) | ✔ |
| Reversing camera | • |

## Transmission & Drive

| | |
|---|---|
| Operation | ✔ |
| Noise | ✔ |
| Clutch | • |
| CV joints | ✔ |
| Wheel bearings | ✔ |
| Wheel balance | ✔ |

## Brakes

| | |
|---|---|
| Performance | ✔ |
| Hand Brake | ✔ |

## Keys & Locking

| | |
|---|---|
| Central locking | ✔ |
| Remote locking | • |
| Number of keys | 1 |

## Engine

| | |
|---|---|
| Oil level | ✔ |
| Smoke & fumes | ✔ |
| Performance | ✔ |
| Noise | ✔ |

## Cooling System

| | |
|---|---|
| Coolant condition | ✔ |
| Performance | ✔ |
| Radiator / Hoses (visual) | ✔ |

## Suspension

| | |
|---|---|
| Suspension performance | ✔ |
| Steering performance | ✔ |
| Shock absorbers | ✔ |

## Tyres (lowest observed tread depth)

| | | |
|---|---|---|
| Left front | 3 | mm |
| Right front | 3 | mm |
| Left rear | 3 | mm |
| Right rear | 3 | mm |
| Spare | Yes | |
| Tools | ✔ | |

## Interior

| | |
|---|---|
| AC Operation | ✔ |
| Heater fan | ✔ |
| Seatbelts | ✔ |
| Horn | ✔ |

**Turners Certified Key**
✔ = Pass ✘ = Fail
• = Not applicable for this vehicle

Inspected by: Daryll Timms Date: 07 Jan 2019

I have read and understood this condition guide. Name: ..... Signature: .....