

Basic Vehicle Condition Guide

Report ID: 17,652,243


Version: 1

Created: 10 Jan 2019

Make: Model: Toyota Caldina **Body Style:** SUV Year: 1998 Registration: CSQ28 Reg Expiry: 18 May 2019 **Odometer:** WoF Expiry: **Good No:** 08 Jun 2019 198,910 Kms 17652243 VIN: 7A8H6240705011784 **Next Service:** 208,000kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Hatch door handle cracked.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy.

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

General Comments

R/H wing mirror adjustment not working. Tidy turbo AWD wagon.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Inspected by:	Daryll Timms	Date:	10 Jan 2019
---------------	--------------	-------	-------------

Name:

	Pass	Fail	N/A
Engine			
Oil level	1		
Smoke & fumes	~		
Performance	V V		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	V V		
Transmission		1	
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	⊥ ≥s)
Left front			mm
Right front		4	mm
Left rear	1	.6	mm
Right rear		2	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			1
Operation	~		
Electrical / Accessories	_		
Head lights	~		
Tail lights			
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	V V V V		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	-	~	
Radio (basic test only)	~		
CD (basic test only)	<i>v</i>		
Number of keys	3		
Central locking	<i>y</i>		
Remote locking	<i>V</i>		
Sat. Nav. (basic test only)			V
Reversing camera			V
eversing curriera			

Signature: