

Basic Vehicle Condition Guide

Report ID: 17,652,420

Version: 1

Created: 07 Feb 2019

 Make:
 Nissan
 Model:
 Dualis
 Body Style:
 SUV


 Year:
 2008
 Registration:
 Reg Expiry:

 WoF Expiry:
 19 Dec 2019
 Odometer:
 102,176 Kms
 Good No:
 17652420

 VIN:
 7AT0DH7HX18000177
 Next Service:
 112150
 Service History:
 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Clean

Interior Comments					
	Seats	Good			
	Carpets	Good			
	Panels	Good			
	Dashboard	Good			

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Stuart Melbourne Date: 07 Feb 2019

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	<i>y y</i>		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	>		
Noise	'		
Clutch	>		
CV joints	VVV		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	>		
Tyres (lowest observed tread	depth	of tyre	es)
Left front		5	mm
Right front		5	mm
Left rear		5	mm
Right rear		5	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		1	
Operation	~		
Electrical / Accessories		1	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	VVV		
Wipers (front & rear)	~		
Window winder FL	\(\times \)		
Window winder FR	~		
Window winder RL	~		
Window winder RR			
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	'		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	'		

Signature: