

## **Turners Certified Imports 50 Point Check**

 Report ID:
 17,652,465

 Version:
 1

 Created:
 08 Feb 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Nissan	Body Style:	Wagon
Model:	Wingroad	Odometer:	64,293 Kms
Year:	2016	VIN:	7AT0DH5GX18185175

Under Carriage & Under Bonnet Inspection Comments Tidy.

	Engine Timir	ng Mechanism:	Timing Chain	
	Dashboard:	Good		
]	Panels:	Good		
	Carpets:	Good		
	Seats:	Good		

Not Applicable

Dry

Evidence of Cam Belt Replacement:

Replaced At (odometer reading):

Road Conditions During Test Drive:

Ger	nera	_0	m	۱m	nei	nts
~	1.0					

Good tidy wagon.

Electrical	Transmission & Drive	Engine	<b>Tyres</b> (lowest observed tread depth)
Battery	Operation	Oil level	Left front 5 mm
Head lights	Noise	Smoke & fumes	Right front 5 mm
Tail lights	Clutch	Performance	Left rear 5 mm
Indicators	CV joints	Noise	Right rear 5 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✓= PassX= Fail●= Not applicable for this vehicle
Reversing camera	Number of keys 2	Inspected by: Daryll Timms	Date: 08 Feb 2019

Name: .....

Signature: .....