

Report ID: 17,654,654 Version: 2 05 Sep 2019 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A
Year:	2006	Registration:	GUB267	Reg Expiry:	02 Jul 2020	Engine	1		1
WoF Expiry:	20 Jun 2020	Odometer:	250,706 Kms	Good No:	17654654	Oil level	~		
VIN:	7AT0CJ3MX13010250	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	S SC	-0	S SC S SC	-01-	S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			TIN	E S	Operation	~		
R = rust PT = paint defe				\prod		Noise	~		
C = crack				+	SC	Clutch	•		~
P = pin dent					741L	CV joints	~		•
* = decals	ssc 916			-NL	ETT SPT	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W S S S S C W S S C						Performance	~		
		Note: som	ne defects & blemishes	mav not be disc	played in the diagram	Hand Brake	~		
Body inspection Comments						Tyres (lowest observed tread	-	of tyre) ^\$)
Clearcoat is coming off vehicle.paint coming off outer door handles. Stonechips on windscreen. Wear on all door cards. Wear on RF seat and seatbelt. AC not cold.						Left front 6 mm			
						Right front	e		 mm
						Left rear			mm
					Right rear			 mm	
Conditions During Body Inspection: Dry						Spare	-		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Engine drive belt noisy. Engine has oil seepage. LF swaybar link worn.						Suspension performance			
	res have bad outer edg			ssing.		Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation		~	
Interior Comments						Electrical / Accessories		V	
Contro	Average					Head lights	~		
Seats						Tail lights	~		
Carpets	Average						~		
	Average								
Panels						Dashboard warning lights Wipers (front & rear)	v		
Dashboa	rd Average					Window winder FL	v		
						Window winder FL Window winder FR	v		
General (Comments						V		
Drives ok.						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Tir	ming Mechanism:	Timina				Remote locking	~		
						Sat. Nav. (basic test only)			~
Lvidence			lot Applicable	11115.		Reversing camera			~
Inspected by: Roger King Date: 05 Sep 2019									

I have read and understood this condition guide.

Name:

Signature: