

Report ID: 17,655,199

Version:

Created: 14 Oct 2019

Fail


N/A

Pass

Make:	Hyundai	Model:	Tucson	Body Style:	SUV
Year:	2009	Registration:	FAC271	Reg Expiry:	12 Dec 2019
WoF Expiry:	06 Aug 2020	Odometer:	189,205 Kms	Good No:	17655199
VIN:	KMHJN81BR9U117389	Next Service:	Service History: No		

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Rear wiper not going. Stonechips on windscreen. LR seatbelt has wear. Wear on RF seat and seatbelt.

Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Engine has oil seepage.

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

## **General Comments**

Inspected by:

Drives ok.

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt

Roger King

**Evidence of Cam Belt Replacement:** No

Kms:

Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\( \triangle \tr		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	2S)
Left front		3	mm
Right front		4	mm
Left rear		1	mm
Right rear	2		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)		~	
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat Nay (basic test only)			<b>_</b>

I have read and understood this condition guide.

Name: .....

Signature: .....

14 Oct 2019

1

Reversing camera