

Basic Vehicle Condition Guide

Report ID: 17,655,286


Version: 2

Created: 24 Oct 2019

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2010 Registration: FRR901 Reg Expiry: 29 Nov 2020 WoF Expiry: **Odometer:** 23 Jan 2020 219,512 Kms **Good No:** 17655286 VIN: MMAJNKA40BD00543 Next Service: 220400 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

 $Head lamps \ need \ buffing. \ Rubber \ trim \ coming \ off \ canopy \ LHS. \ Canopy \ tailgate \ rubber \ worn. \ Stone chips \ on \ an expectation \ and \ an expectation \ an expectation \ and \ an expectation \ an expectation \ and \ an expectation \ and \ an expectation \ an expectation \ and \ an expectation \ and \ an expectation \ an expectation \ and \ an expectation \ an expectation \ and \ an expectation \ an expectation \ and \ an expectation \ and \ an expectation \ an expectation \ and \ an expectation \ an expectation \ an expectation \ and \ an expectation \ an expectation \ and \ an expectation \ and \ an expectation \ an expectation \ and \ an expectation \ and \ an expectation \ an expectation \ and \ an expectation \ and \ an expectation \ an expectation \ an expectation \ an expectation \ and \ an expectation \ an expect$ windscreen. Clearcoat is coming off vehicle. Paint damage on canopy and bonnet. RF seat is worn.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine and steering rack have oil seepage.

<u>Interior Comments</u>		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

General Comments

Noise in rear of vehicle, suspect differential.

Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Kms: 129,049 Yes

24 Oct 2019 Inspected by: Roger King Date:

Name:

	_		
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes	•		
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front 2		2	mm
Right front	3		mm
Left rear	3		mm
Right rear	2		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	V V V V V V V V		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	1		
Sat. Nav. (basic test only)	•		~

Signature: