

Report ID: 17,656,225 Version: 4 03 Dec 2019 Created:

Make:	Hyundai	Model:	130	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2014	Registration:	HNA811	Reg Expiry:	28 Sep 2020	Engine			
WoF Expiry:	12 Jul 2020	Odometer:	151,949 Kms	Good No:	17656225	Oil level	~		
VIN:	KMHD251EMEU19946	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		<b>(</b> ) )		1 12 11 1	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	sc	-0	S P SC S P SC		S SC	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO	<u>E</u>		X	Transmission	•		I
D = dent						Operation V			
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack				+	SC	Clutch	•		~
P = pin dent	Ho					CV joints	~		
* = decals	PSC PSC			AL.	ELIPE S	Wheel bearings	~		
SC = stone chi	ps US	V A		JAL)	& <u> </u>	Brakes	V		
W = significant scuffs S SC S P S P SC S SC S SC						Performance	~		
		Note: com				Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							, i		
Stonechips on windscreen. Wear on steering wheel.						Tyres (lowest observed tread depth of tyres)			
wear on ste	ening wheel.					Left front	7		mm
						Right front	7		mm
						Left rear	1.0		mm
Conditions During Body Inspection: Dry						Right rear	2 mm		
Under Carriege & Under Depart Ingrestion Comments					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Good cond	ition.					Suspension performance	~		ļ
						Steering performance	~		ļ!
						Shock absorbers	~		
						Air Conditioning / Heater			
Interview Commonte						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Deskte	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Drives well.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
с							ı İ		
Inspecte	d by: Roger King					Date: 03 Dec 20	19		

I have read and understood this condition guide.

Name: .....

Signature: .....