

# **Basic Vehicle Condition Guide**

Report ID: 17,656,512


Version: 1

Created: 29 Oct 2019

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2006 Registration: **DLT801** Reg Expiry: 25 Oct 2019 WoF Expiry: **Odometer:** 15 May 2020 302,722 Kms **Good No:** 17656512 VIN: MR0HZ22G203502751 Next Service: 308000 Service History:

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



#### **Body Inspection Comments**

Tray headboard has damage. Stonechips on windscreen. Aerial bent. LH running board is bent. Both drink holders in dash are damaged. RF seat is worn. Ignition key falls out when driving.

Conditions During Body Inspection: Wet

### **Under Carriage & Under Bonnet Inspection Comments**

Gearbox has whine and oil seepage.

<u>Interior Comments</u>				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

## **General Comments**

Inspected by:

Drives ok.

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt

Roger King

**Evidence of Cam Belt Replacement:** Kms: 200,000 Yes

- Create			
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\( \times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	~		
CV joints	\( \triangle \)		
Wheel bearings	~		
Brakes	•	•	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	(	5	mm
Right front	(	5	mm
Left rear	6		mm
Right rear	6		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	ı		1
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	<b>v</b>		
Indicators	~		
Dashboard warning lights	\( \triangle \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	<i>'</i>		
Remote locking			~
Sat. Nav. (basic test only)			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Reversing camera			<i>\'\'</i>
eversing carriera			

I have read and understood this condition guide.

Name: .....

Signature: .....

29 Oct 2019

Date: