

Report ID: 17,657,037 Version: 1 14 Nov 2019 Created:

Make:	Honda	Model:	FIT	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	Registration:	LWK596	<b>Reg Expiry:</b>	03 Nov 2020	Engine			
WoF Expiry:	18 Mar 2020	Odometer:	46,734 Kms	Good No:	17657037	Oil level	~		
VIN:	7AT08G2YX19008196	Next Service:	52053	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	<u>s</u>	-01-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	sc d			710	HIV	Operation	~		
PT = paint defe		r I		$\left[ \left( \right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	sc de				7411L	CV joints	~		
* = decals				10	ELD'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	SC		S			Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread	depth	of tyre	es)
Wear on RF seatbelt.						Left front	5 mm		
						Right front	6	5	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Good condi	tion.					Suspension performance	~		
						Steering performance	~		
Sh						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Daabhaa	Good					Wipers (front & rear)	~		
Dashboa	iu					Window winder FL	~		
					]	Window winder FR	~		
General Comments						Window winder RL	~		
Drives well.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry							~		
Engine Timing Mechanismu Timing Chain						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Roger King Date: 14 Nov 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....