



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	17,659,849
Version:	2
Created:	06 Sep 2019

Make:	Mazda	Body Style:	Hatchback
Model:	Demio	VIN:	7AT0C12HX19121507
Year:	2009	Odometer:	85,097 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good		
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good		
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good		
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	85	R/H Mirror	Good	86	L/H Mirror	Good
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	Wheels and Tyres		87	L/F Guard	Good	88	R/F Guard	Good
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	3	mm	89	L/H Doors	Good	90	R/H Doors	Good	
7	Rear Right Indicators	✓	37	CV Joints	✓	62	Right Front	3	mm	91	L/H Sill	Good	92	R/H Sill	Good	
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	63	Left Rear	3	mm	93	Boot/Tail Gate	Good	94	Front Bumper	Good	
9	Reversing Lights	✓	39	Wheel Balance	✓	64	Right Rear	3	mm	95	Rear Bumper	Good	96	Roof	Good	
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	65	Spare	Yes	97	Bonnet	Good	98	Fuel Cap	✓		
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	66	Tools	✓	99	Mud Flaps	✓	100	WOF	✓		
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	Interior		67	AC Operation	✓						
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		68	Heater Fan	✓	69	Seatbelts	✓					
14	Dashboard Dimmer Switch	•	Brakes		44	Front Brakes	✓	70	Horn	✓						
15	Number Plate Light	✓	45	Rear Brakes	✓	46	Handbrake	✓	71	Seat Heaters	•					
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓	72	Sun Visors	✓						
17	Speedo	✓	48	Remote Locking	✓	49	Number of Keys	2	73	Sun Visors Lights/Mirrors	✓					
18	Odometer	✓	Engine		50	Oil Level	✓	74	Seats	Good						
19	Rev Counter	✓	51	Smokes and Fumes	✓	52	Performance	✓	75	Carpets	Good					
20	Fuel Gauge	✓	53	Noise	✓	54	Starter Motor	✓	76	Panels	Good					
21	Wipers Front/Rear	✓							77	Dashboard	Good					
22	Window Opener FL	✓														
23	Window Opener FR	✓														
24	Window Opener RL	✓														
25	Window Opener RR	✓														
26	Rear View Mirrors	✓														
27	Radio (Basic Test Only)	✓														
28	CD (Basic Test Only)	✓														
29	Boot Open Switch	✓														

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Kyle Mills-Brown	Date:	06 Sep 2019
I have read and understood this condition guide:			
Name:		Signature:	