

## **Basic Vehicle Condition Guide**

Report ID: 17,663,256


Version: 5

Created: 03 Dec 2019

Make: Model: Mazda Axela **Body Style:** Hatchback Year: 2006 Registration: KAZ697 Reg Expiry: 29 Feb 2020 **WoF Expiry: Odometer:** 19 Jul 2020 115,653 Kms **Good No:** 17663256 VIN: **Next Service:** 7AT0C13JX15203589 126000 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Dirty

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Stuart Melbourne Date: 28 Jun 2019

	1	1	
	Pass	Fail	N/A
Engine	1 .		
Oil level	-		
Smoke & fumes	<b>V</b>		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	2	.8	mm
Right front	3.2		mm
Left rear	5	.4	mm
Right rear	5.7		mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	~		
Shock absorbers	<i>'</i>		
Air Conditioning / Heater			
Operation			Ι
Electrical / Accessories			
Head lights	.,		Г
Tail lights	<i>'</i>		
	~		
Indicators	<b>'</b>		
Dashboard warning lights	<b>'</b>		
Wipers (front & rear)	~		
Window winder FL	V		
Window winder FR	<b>/</b>		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~

I have read and understood this condition guide.

Name:			