

Basic Vehicle Condition Guide

Report ID: 17,663,260

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Coolant condition
Performance

Radiator / Hoses (visual)

Created: 24 Jul 2019

Pass

1

V

/

V

1

Tyres (lowest observed tread depth of tyres)

N/A

1

mm

mm

mm

4.0

4.0


7.0

Fail

Make: Model: Honda Inspire **Body Style:** Sedan Year: 2004 Registration: LMG403 **Reg Expiry:** 28 Dec 2019 WoF Expiry: **Odometer:** 25 Jul 2020 96,381 Kms **Good No:** 17663260 VIN: 7AT08G0TX17050151 **Next Service:** 104326 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Stone chips front screen. Central locking not working on left front door

Conditions During Body Inspection: Dry

<u>Under Carriage & Under Bonnet Inspection Comments</u>

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

_	_
Conoral	Comments
General	COMMENTS

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

Name:

Right rear 6.0 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) Reversing camera 2019 Signature:

Inspected by:	Brian Hill	Date:	28 Jun 2
---------------	------------	-------	----------