

Report ID: 17,663,336 Version: 1 25 Jul 2019 Created:

Make:	Suzuki	Model:	Escudo	Body Style:	SUV		Pass	Fail	N/A
Year:	2009	Registration:		Reg Expiry:		Engine			
WoF Expiry:		Odometer:	80,988 Kms	Good No:	17663336	Oil level	~		
VIN:	7AT0GK4MX19104069	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
		_				Performance	レ レ		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent					BID				
R = rust	MIP			10		Operation	~		
PT = paint def C = crack	ect			$ \cup$		Noise Clutch	~		
C = Crack P = pin dent	Ho								~
* = decals	dic					CV joints	~		
SC = stone chi	ps US			10	\$P	Wheel bearings	~		
W = significant scuffs						Brakes			
						Performance	~		
Body Ins	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	7	7	mm
						Right front	7	7	mm
						Left rear	8	3	mm
Conditions During Body Inspection: Dry						Right rear	8 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	<		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		L
Road Conditions During Test Drive: Dry						Central locking	· ·		
Road Con	ations During Test	Drive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	-		
Evidence of Cam Belt Replacement: Not Applicable Kms:									v
						Reversing camera			~
Inspected by: Brian Hill Date: 25 Jul 2019									

I have read and understood this condition guide.

Name:

Signature: