



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	17,663,343
Version:	1
Created:	19 Jul 2019

Make:	Toyota	Body Style:	SUV
Model:	Isis	VIN:	7AT0H658X19062891
Year:	2006	Odometer:	52,799 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	
4	High Stop Light	✓	Transmission and Drive		Wheels and Tyres		59	Steering Performance	✓	60	Shock Absorbers	✓	85	R/H Mirror	Good		
5	Front Right Indicators	✓	34	Operation	✓	61	Left Front	7	mm	62	Right Front	7	mm	86	L/H Mirror	Good	
6	Front Left Indicators	✓	35	Noise	✓	63	Left Rear	7	mm	64	Right Rear	7	mm	87	L/F Guard	Good	
7	Rear Right Indicators	✓	36	Clutch	•	65	Left Rear	7	mm	66	Right Rear	7	mm	88	R/F Guard	Good	
8	Rear Left Indicators	✓	37	CV Joints	✓	67	Left Rear	7	mm	68	Right Rear	7	mm	89	L/H Doors	Good	
9	Reversing Lights	✓	38	Wheel Bearing	✓	69	Left Rear	7	mm	70	Right Rear	7	mm	90	R/H Doors	Good	
10	Rear Reflectors	✓	39	Wheel Balance	✓	71	Left Rear	7	mm	72	Right Rear	7	mm	91	L/H Doors	Good	
11	Hazard Lights	✓	40	Gearbox (Manual)	•	73	Left Rear	7	mm	74	Right Rear	7	mm	92	R/H Doors	Good	
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	75	Left Rear	7	mm	76	Right Rear	7	mm	93	L/H Doors	Good	
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	77	Left Rear	7	mm	78	Right Rear	7	mm	94	R/H Doors	Good	
14	Dashboard Dimmer Switch	•	43	Replaced at (odometer reading)		79	Left Rear	7	mm	80	Right Rear	7	mm	95	L/H Doors	Good	
15	Number Plate Light	✓	Brakes		Interior		81	Left Front	7	mm	82	Right Front	7	mm	96	R/H Doors	Good
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	83	Left Front	7	mm	84	Right Front	7	mm	97	L/H Doors	Good	
17	Speedo	✓	45	Rear Brakes	✓	85	Left Front	7	mm	86	Right Front	7	mm	98	R/H Doors	Good	
18	Odometer	✓	46	Handbrake	✓	87	Left Front	7	mm	88	Right Front	7	mm	99	L/H Doors	Good	
19	Rev Counter	✓	Keys and Locking		89	Left Front	7	mm	90	Right Front	7	mm	91	R/H Doors	Good		
20	Fuel Gauge	✓	47	Central Locking	✓	91	Left Front	7	mm	92	Right Front	7	mm	93	L/H Doors	Good	
21	Wipers Front/Rear	✓	48	Remote Locking	✓	93	Left Front	7	mm	94	Right Front	7	mm	95	R/H Doors	Good	
22	Window Opener FL	✓	49	Number of Keys	1	95	Left Front	7	mm	96	Right Front	7	mm	97	L/H Doors	Good	
23	Window Opener FR	✓	Engine		97	Left Front	7	mm	98	Right Front	7	mm	99	R/H Doors	Good		
24	Window Opener RL	✓	50	Oil Level	✓	99	Left Front	7	mm	100	Right Front	7	mm	101	L/H Doors	Good	
25	Window Opener RR	✓	51	Smokes and Fumes	✓	101	Left Front	7	mm	102	Right Front	7	mm	103	R/H Doors	Good	
26	Rear View Mirrors	✓	52	Performance	✓	103	Left Front	7	mm	104	Right Front	7	mm	105	L/H Doors	Good	
27	Radio (Basic Test Only)	✓	53	Noise	✓	105	Left Front	7	mm	106	Right Front	7	mm	107	R/H Doors	Good	
28	CD (Basic Test Only)	✓	54	Starter Motor	✓	107	Left Front	7	mm	108	Right Front	7	mm	109	L/H Doors	Good	
29	Boot Open Switch	✓				109	Left Front	7	mm	110	Right Front	7	mm	111	R/H Doors	Good	

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Daryll Timms	Date:	19 Jul 2019
---------------	--------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--