



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	17,663,358
Version:	1
Created:	18 Jul 2019

Make:	Subaru	Body Style:	Wagon
Model:	Legacy	VIN:	7AT0GF0BX19136225
Year:	2006	Odometer:	36,590 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good																																																									
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good																																																									
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good																																																									
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good																																																										
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good																																																										
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good																																																										
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	7	mm	86	L/H Mirror	Good																																																											
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>7</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	7	mm	87	L/F Guard	Good																																																											
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>63</td> <td>Left Rear</td> <td>7</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	63	Left Rear	7	mm	88	R/F Guard	Good																																																											
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>7</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	64	Right Rear	7	mm	89	L/H Doors	Good																																																											
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	65	Spare	Yes	90	R/H Doors	Good																																																												
11	Hazard Lights	✓	41	Engine Timing	Cambelt	66	Tools	✓	91	L/H Sill	Good																																																												
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	No	Interior		67	AC Operation	✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>	92	R/H Sill	Good																																																										
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>93</td><td>Boot/Tail Gate</td><td>Good</td></th>	69	Seatbelts	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	93	Boot/Tail Gate	Good																																																									
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>70</td> <td>Horn</td> <th>✓<td>71</td><td>Seat Heaters</td><th>•</th><td>94</td><td>Front Bumper</td><td>Good</td></th>	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <th>•</th> <td>94</td> <td>Front Bumper</td> <td>Good</td>	71	Seat Heaters	•	94	Front Bumper	Good																																																							
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>72</td><td>Sun Visors</td><th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th></th></th>	46	Handbrake	✓ <td>72</td> <td>Sun Visors</td> <th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th></th>	72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td>	95	Rear Bumper	Good																																																						
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>75</td> <td>Carpets</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td>	74	Seats	Good	75	Carpets	Good	96	Roof	Good																																																							
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>2</td> <td>76</td> <td>Panels</td> <td>Good</td> <td>77</td> <td>Dashboard</td> <td>Good</td> <td>97</td> <td>Bonnet</td> <td>Good</td>	49	Number of Keys	2	76	Panels	Good	77	Dashboard	Good	97	Bonnet	Good																																																						
18	Odometer	✓	Engine		50	Oil Level	✓ <td>51</td> <td>Smokes and Fumes</td> <th>✓<td>52</td><td>Performance</td><th>✓<td>53</td><td>Noise</td><th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th></th></th>	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>53</td><td>Noise</td><th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th></th>	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th>	53	Noise	✓ <td>98</td> <td>Fuel Cap</td> <th>✓</th>	98	Fuel Cap	✓																																																				
19	Rev Counter	✓	54	Starter Motor	✓ <td>55</td> <td>Smokes and Fumes</td> <th>✓<td>56</td><td>Performance</td><th>✓<td>57</td><td>Radiator/Hoses (visual)</td><th>✓<td>58</td><td>Suspension Performance</td><th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th></th></th></th>	55	Smokes and Fumes	✓ <td>56</td> <td>Performance</td> <th>✓<td>57</td><td>Radiator/Hoses (visual)</td><th>✓<td>58</td><td>Suspension Performance</td><th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th></th></th>	56	Performance	✓ <td>57</td> <td>Radiator/Hoses (visual)</td> <th>✓<td>58</td><td>Suspension Performance</td><th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th></th>	57	Radiator/Hoses (visual)	✓ <td>58</td> <td>Suspension Performance</td> <th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th>	58	Suspension Performance	✓ <td>99</td> <td>Mud Flaps</td> <th>✓</th>	99	Mud Flaps	✓																																																			
20	Fuel Gauge	✓	59	Steering Performance	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>61</td><td>Left Front</td><td>7</td><td>mm</td><td>62</td><td>Right Front</td><td>7</td><td>mm</td><td>63</td><td>Left Rear</td><td>7</td><td>mm</td><td>64</td><td>Right Rear</td><td>7</td><td>mm</td><td>65</td><td>Spare</td><td>Yes</td><td>66</td><td>Tools</td><th>✓<td>67</td><td>AC Operation</td><th>✓<td>68</td><td>Heater Fan</td><th>✓<td>69</td><td>Seatbelts</td><th>✓<td>70</td><td>Horn</td><th>✓<td>71</td><td>Seat Heaters</td><th>•<td>72</td><td>Sun Visors</td><th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>74</td><td>Seats</td><td>Good</td><td>75</td><td>Carpets</td><td>Good</td><td>76</td><td>Panels</td><td>Good</td><td>77</td><td>Dashboard</td><td>Good</td></th></th></th></th></th></th></th></th></th>	60	Shock Absorbers	✓ <td>61</td> <td>Left Front</td> <td>7</td> <td>mm</td> <td>62</td> <td>Right Front</td> <td>7</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>7</td> <td>mm</td> <td>64</td> <td>Right Rear</td> <td>7</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>Yes</td> <td>66</td> <td>Tools</td> <th>✓<td>67</td><td>AC Operation</td><th>✓<td>68</td><td>Heater Fan</td><th>✓<td>69</td><td>Seatbelts</td><th>✓<td>70</td><td>Horn</td><th>✓<td>71</td><td>Seat Heaters</td><th>•<td>72</td><td>Sun Visors</td><th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>74</td><td>Seats</td><td>Good</td><td>75</td><td>Carpets</td><td>Good</td><td>76</td><td>Panels</td><td>Good</td><td>77</td><td>Dashboard</td><td>Good</td></th></th></th></th></th></th></th></th>	61	Left Front	7	mm	62	Right Front	7	mm	63	Left Rear	7	mm	64	Right Rear	7	mm	65	Spare	Yes	66	Tools	✓ <td>67</td> <td>AC Operation</td> <th>✓<td>68</td><td>Heater Fan</td><th>✓<td>69</td><td>Seatbelts</td><th>✓<td>70</td><td>Horn</td><th>✓<td>71</td><td>Seat Heaters</td><th>•<td>72</td><td>Sun Visors</td><th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>74</td><td>Seats</td><td>Good</td><td>75</td><td>Carpets</td><td>Good</td><td>76</td><td>Panels</td><td>Good</td><td>77</td><td>Dashboard</td><td>Good</td></th></th></th></th></th></th></th>	67	AC Operation	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>69</td><td>Seatbelts</td><th>✓<td>70</td><td>Horn</td><th>✓<td>71</td><td>Seat Heaters</td><th>•<td>72</td><td>Sun Visors</td><th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>74</td><td>Seats</td><td>Good</td><td>75</td><td>Carpets</td><td>Good</td><td>76</td><td>Panels</td><td>Good</td><td>77</td><td>Dashboard</td><td>Good</td></th></th></th></th></th></th>	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>70</td><td>Horn</td><th>✓<td>71</td><td>Seat Heaters</td><th>•<td>72</td><td>Sun Visors</td><th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>74</td><td>Seats</td><td>Good</td><td>75</td><td>Carpets</td><td>Good</td><td>76</td><td>Panels</td><td>Good</td><td>77</td><td>Dashboard</td><td>Good</td></th></th></th></th></th>	69	Seatbelts	✓ <td>70</td> <td>Horn</td> <th>✓<td>71</td><td>Seat Heaters</td><th>•<td>72</td><td>Sun Visors</td><th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>74</td><td>Seats</td><td>Good</td><td>75</td><td>Carpets</td><td>Good</td><td>76</td><td>Panels</td><td>Good</td><td>77</td><td>Dashboard</td><td>Good</td></th></th></th></th>	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <th>•<td>72</td><td>Sun Visors</td><th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>74</td><td>Seats</td><td>Good</td><td>75</td><td>Carpets</td><td>Good</td><td>76</td><td>Panels</td><td>Good</td><td>77</td><td>Dashboard</td><td>Good</td></th></th></th>	71	Seat Heaters	• <td>72</td> <td>Sun Visors</td> <th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>74</td><td>Seats</td><td>Good</td><td>75</td><td>Carpets</td><td>Good</td><td>76</td><td>Panels</td><td>Good</td><td>77</td><td>Dashboard</td><td>Good</td></th></th>	72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>74</td><td>Seats</td><td>Good</td><td>75</td><td>Carpets</td><td>Good</td><td>76</td><td>Panels</td><td>Good</td><td>77</td><td>Dashboard</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>75</td> <td>Carpets</td> <td>Good</td> <td>76</td> <td>Panels</td> <td>Good</td> <td>77</td> <td>Dashboard</td> <td>Good</td>	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good								
21	Wipers Front/Rear	✓	78	Under Carriage	Good	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	85	R/H Mirror	Good	86	L/H Mirror	Good	87	L/F Guard	Good	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓
22	Window Opener FL	✓	Turners Certification Key:																																																																				
23	Window Opener FR	✓	✓ = Pass																																																																				
24	Window Opener RL	✓	✗ = Fail																																																																				
25	Window Opener RR	✓	• = Not applicable for this vehicle																																																																				
26	Rear View Mirrors	✓																																																																					
27	Radio (Basic Test Only)	✓																																																																					
28	CD (Basic Test Only)	✓																																																																					
29	Boot Open Switch	✓																																																																					

Inspected by:	Daryll Timms	Date:	18 Jul 2019
---------------	--------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--