

Report ID: 17,663,475


Version: 1

Created: 02 Jul 2019

| Make: | Hyundai | Model: | 130 | Body Style: | Hatchback |
|-------------|------------------|---------------|-------------|----------------|----------------|
| Year: | 2010 | Registration: | FLF408 | Reg Expiry: | 04 Sep 2019 |
| WoF Expiry: | 09 Jul 2020 | Odometer: | 227,206 Kms | Good No: | 17663475 |
| VIN: | KMHDC51TMAU26216 | Next Service: | 236,000kms | Service Histor | r y: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Rear tow hook cover missing. Small crack in r/h tail light. Fine chips on screen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

OK, dirty.

| <u>Interior Comments</u> | | | | | |
|--------------------------|-----------------------------|--|--|--|--|
| Seats | Average | | | | |
| Carpets | Average | | | | |
| Panels | door handle chrome peeling. | | | | |
| Dashboard | steering wheel worn. | | | | |

General Comments

Good hatch.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Daryll Timms 02 Jul 2019 Inspected by: Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|-----------------------|----------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | <i>y y</i> | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | | |
| Operation | ~ | | |
| Noise | V | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | 1 |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | | 4 | mm |
| Right front | | 5 | mm |
| Left rear | | 5 | mm |
| Right rear | | 5 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | <i>V</i> | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | ı | | ı |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | V V V V V | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | <u> </u> | 1 |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |
| | | | |

Signature: