

Basic Vehicle Condition Guide

Report ID: 17,663,803


Version: 1

09 Jul 2019 Created:

Make: Model: Holden Colorado **Body Style:** Utility Year: 2013 Registration: HDU317 Reg Expiry: 27 Aug 2019 WoF Expiry: **Odometer: Good No:** 23 Nov 2019 195,042 Kms 17663803 VIN: MMU148EK0EH60902 Next Service: 196749 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Dirty

Interior Comments			
Seats	RF worn		
Carpets	Average		
Panels	Average		
Dashboard	Good		

Genera	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	~				
Performance	\(\triangle \)				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	~				
Radiator / Hoses (visual)	V				
Transmission					
Operation	~				
Noise	~				
Clutch			~		
CV joints			~		
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed treac	depth	of tyre	:s)		
Left front	4	.4	mm		
Right front	5	.2	mm		
Left rear	5	.1	mm		
Right rear	5	.1	mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	V				
Shock absorbers	~				
Air Conditioning / Heater			ı		
Operation	~				
Electrical / Accessories					
Head lights	~				
Tail lights					
Indicators	V				
Dashboard warning lights	V				
Wipers (front & rear)	~				
Window winder FL	VVV				
Window winder FR	~				
Window winder RL	~				
Window winder RR	~				
Rear view mirrors	~				
Radio (basic test only)	~				
CD (basic test only)			~		
Number of keys	4				
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)			~		
Reversing camera	~				
Date: 00 lul 2010					

I have read and understood this condition guide.

Stuart Melbourne

Name:

Signature:

Date: 09 Jul 2019