



Turners Certified Imports 50 Point Check

Report ID: 17,668,950

Version: 1

Created: 28 Jan 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Subaru Body Style: SUV
Model: Forester Odometer: 120,874 Kms
Year: 2008 VIN: 7AT0GF17X19004157

Under Carriage & Under Bonnet Inspection Comments

Tidy .

General Comments

Tidy turbo manual AWD wagon .

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Replaced At (odometer reading):

Road Conditions During Test Drive: Dry

Electrical

Battery ☒
Head lights ☒
Tail lights ☒
Indicators ☒
Dashboard warning lights ☒
Wipers (front & rear) ☒
Window winder FL ☒
Window winder FR ☒
Window winder RL ☒
Window winder RR ☒
Rear view mirrors ☒
Radio (basic test only) ☒
CD (basic test only) ☒
Reversing camera ☒

Transmission & Drive

Operation ☒
Noise ☒
Clutch ☒
CV joints ☒
Wheel bearings ☒
Wheel balance ☒

Brakes

Performance ☒
Hand Brake ☒

Keys & Locking

Central locking ☒
Remote locking ☒
Number of keys

Engine

Oil level ☒
Smoke & fumes ☒
Performance ☒
Noise ☒

Cooling System

Coolant condition ☒
Performance ☒
Radiator / Hoses (visual) ☒

Suspension

Suspension performance ☒
Steering performance ☒
Shock absorbers ☒

Tyres (lowest observed tread depth)

Left front mm
Right front mm
Left rear mm
Right rear mm
Spare
Tools ☒

Interior

AC Operation ☒
Heater fan ☒
Seatbelts ☒
Horn ☒

Turners Certified Key

✓ = Pass X = Fail
• = Not applicable for this vehicle

Inspected by: Daryll Timms

Date: 28 Jan 2019

I have read and understood this condition guide.

Name:

Signature: