

 Report ID:
 17,669,264

 Version:
 1

 Created:
 27 Jun 2019

Make:	Holden	Model:	Cruze	Body Style:	Wagon		Pass	Fail	N/A
Year:	2015	Registration:	HWK824	Reg Expiry:	15 Apr 2019	Engine	•		
WoF Expiry:	17 Jan 2020	Odometer:	67,701 Kms	Good No:	17669264	Oil level	~		
VIN:	KL3JA35MJEK617861	Next Service:	82000	Service Histor	' y: No	Smoke & fumes	~		
	_					Performance	~		
	port is not a warranty s a guide only. Consid		for age and mileage	Parts have not	t been dismantled or	Noise	V		
diagnostic te	sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System	1		4
a full mechar	nical inspection prior to	purchase and t	his can be arranged fo	or an additional	charge.	Coolant condition	~		
						Performance	V		
Key:	SC M	-0	PP	-161-	Р	Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent				TIN		Operation	~		
R = rust PT = paint def	NIP			\prod	JUIL	Noise	~		
C = crack				+		Clutch	-		~
P = pin dent	Htc					CV joints	~		
* = decals	sc 1916				ELLER S	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs W P S P S D						Performance	~		1
		Note: sor	ne defects & blemishes	may not be disr	played in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	oftyre	
Chip screen						Tyres (lowest observed tread depth of tyres) Left front 7			
						Right front			mm
						Left rear		7	
						n		7	mm
Conditions During Body Inspection: Wet						Right rear		7	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
		meenspeen				Suspension		1	1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1	1	T
Interior Comments						Operation	~		
Good						Electrical / Accessories	1	1	T
Seats						Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		
	Good					Indicators	~		<u> </u>
Panels	3000					Dashboard warning lights	~		<u> </u>
Dashboa	ard Good					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
						Window winder FR	~		
General Comments						Window winder RL	~		
Flat battery. Electric steer						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
·									
Inspected by: Stuart Melbourne Date: 27 Jun 2019									

I have read and understood this condition guide.

Name:

Signature: