

Basic Vehicle Condition Guide

Report ID: 17,669,860


Version: 1

Created: 24 Jan 2019

Make: Model: Toyota Highlander **Body Style:** SUV Year: 2015 Registration: HZL126 Reg Expiry: 25 Mar 2019 WoF Expiry: **Odometer: Good No:** 07 May 2019 103,599 Kms 17669860 VIN: 5TDBK3FH60S116494 **Next Service:** 10k overdue Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & plemisnes may not be displayed in the d

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | |
|-------------------|-------------------|--|
| Seats | Drivers seat worn | |
| Carpets | Good | |
| Panels | Good | |
| Dashboard | Good | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Murray Craig Date: 24 Jan 2019

| | Pass | Fail | N/A | |
|------------------------------|----------------------------|---------|-----|--|
| Engine | | • | | |
| Oil level | ~ | | | |
| Smoke & fumes | <i>v</i> | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | • | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | • | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | |
| Left front | | 7 | mm | |
| Right front | | 7 | mm | |
| Left rear | | 7 | mm | |
| Right rear | 7 | | mm | |
| Spare | | Yes | | |
| Suspension | • | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | • | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | V V V V V V | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 3 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |
| | • | • | • | |

I have read and understood this condition guide.

Name:

Signature: