

Report ID: 17,670,362 Version: 1 Created: 31 Jan 2019

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:		Reg Expiry:		Engine	1	I	<u> </u>
WoF Expiry:	21 Jan 2020	Odometer:	73,091 Kms	Good No:	17670362	Oil level	~		
VIN:	WVWZZZ1KZ8U01252	Next Service:	83675	Service Histor	r y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	oration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	~		
diagnostic te	sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		1
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		+
S = scratch	RE	A U			The second	Transmission			<u> </u>
D = dent	- GIE			TIN		Operation	~		Τ
R = rust PT = paint def				r In	JUIL	Noise	~		+
C = crack						Clutch			~
P = pin dent						CV joints	~		-
* = decals	616			AL.		Wheel bearings	~		
SC = stone chips						Brakes	v		
W = significant scuffs						Performance	~		1
		Note: con	ne defects & blemishes		alayed in the diagram	Hand Brake	~		
	pection Comments	Note: 3011	le delects & blemisnes	s may not be disp	bayed in the diagram		•	ofter	
Good condition						Tyres (lowest observed tread depth of tyres)			
						Left front		4	mm
						Right front		4	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	mermspectic	<u>on comments</u>			Suspension		1	,
Clean						Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Correcto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
						Window winder FR	~		1
<u>General Comments</u>						Window winder RL	~		1
						Window winder RR	~		1
						Rear view mirrors	~		+
						Radio (basic test only)	~		+
						CD (basic test only)	~		+
						Number of keys	1	I	
Road Conditions During Test Drive: Dry						Central locking	~		
			Dry			Remote locking	~		+
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
						<u> </u>			<u> </u>
Inspecte	d by: Stuart Melbourr	ne				Date: 31 Jan 20	19		

I have read and understood this condition guide.

Name:

Signature: