

Report ID: 17,670,740 Version: 1 25 Jan 2019 Created:

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail	N/A
Year:	2007	Registration:	EDH604	Reg Expiry:	20 Sep 2019	Engine			
WoF Expiry:	13 Jul 2019	Odometer:	339,230 Kms	Good No:	17670740	Oil level	~		
VIN:	6G1EK52B48L971410	Next Service:	349000	Service Histor	y: No	Smoke & fumes	V		
	_					Performance	V		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC					Performance	V		
Key:	Lise (-0		-(M-		Radiator / Hoses (visual)	V		
S = scratch D = dent						Transmission			
D = dent R = rust	PT SC			715	HIVOW	Operation	~		
PT = paint defe		FI		$\left(\left \left(\right) \right\rangle \right)$		Noise	V		
C = crack					SC	Clutch			~
P = pin dent	HID				74116	CV joints			~
* = decals	sc 616					Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W SC						Performance	~		
Bodylog	action Commonts	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			1 2S)
Wiper mark and stone chips front screen. Drivers seat base trim panel broken. Number plate light not working.						Left front 3 mm			
_						Right front		3	mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear		5	mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		$\left - \right $
	I					Window winder FR	~		<u> </u>
General C	<u>Comments</u>					Window winder RL	~		$\left - \right $
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		$\left - \right $
						Radio (basic test only)	~		$\left - \right $
						CD (basic test only)	~		
						Number of keys	1		L
Road Conditions During Test Drive: Dry						Central locking			
Road Con	ations During Test	L Drive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	-		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~ ~
Inspected by: Brian Hill Date: 25 Jan 2019									

I have read and understood this condition guide.

Name:

Signature: