



Turners Certified Imports 50 Point Check

Report ID: 17,671,199
Version: 1
Created: 01 Feb 2019

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Mitsubishi	Body Style: Hatchback
Model: Galant	Odometer: 98,288 Kms
Year: 2013	VIN: 7AT0CJOJX19300387

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Under Carriage & Under Bonnet Inspection Comments
Tidy.

Engine Timing Mechanism:	Timing Chain
Evidence of Cam Belt Replacement:	Not Applicable
Replaced At (odometer reading):	
Road Conditions During Test Drive:	Dry

General Comments
Nice tidy hatch.

Electrical	
Battery	<input checked="" type="checkbox"/>
Head lights	<input checked="" type="checkbox"/>
Tail lights	<input checked="" type="checkbox"/>
Indicators	<input checked="" type="checkbox"/>
Dashboard warning lights	<input checked="" type="checkbox"/>
Wipers (front & rear)	<input checked="" type="checkbox"/>
Window winder FL	<input checked="" type="checkbox"/>
Window winder FR	<input checked="" type="checkbox"/>
Window winder RL	<input checked="" type="checkbox"/>
Window winder RR	<input checked="" type="checkbox"/>
Rear view mirrors	<input checked="" type="checkbox"/>
Radio (basic test only)	<input checked="" type="checkbox"/>
CD (basic test only)	<input checked="" type="checkbox"/>
Reversing camera	<input type="checkbox"/>

Transmission & Drive	
Operation	<input checked="" type="checkbox"/>
Noise	<input checked="" type="checkbox"/>
Clutch	<input type="checkbox"/>
CV joints	<input checked="" type="checkbox"/>
Wheel bearings	<input checked="" type="checkbox"/>
Wheel balance	<input checked="" type="checkbox"/>
Brakes	
Performance	<input checked="" type="checkbox"/>
Hand Brake	<input checked="" type="checkbox"/>
Keys & Locking	
Central locking	<input checked="" type="checkbox"/>
Remote locking	<input checked="" type="checkbox"/>
Number of keys	<input type="text" value="1"/>

Engine	
Oil level	<input checked="" type="checkbox"/>
Smoke & fumes	<input checked="" type="checkbox"/>
Performance	<input checked="" type="checkbox"/>
Noise	<input checked="" type="checkbox"/>
Cooling System	
Coolant condition	<input checked="" type="checkbox"/>
Performance	<input checked="" type="checkbox"/>
Radiator / Hoses (visual)	<input checked="" type="checkbox"/>
Suspension	
Suspension performance	<input checked="" type="checkbox"/>
Steering performance	<input checked="" type="checkbox"/>
Shock absorbers	<input checked="" type="checkbox"/>

Tyres (lowest observed tread depth)	
Left front	<input type="text" value="5"/> mm
Right front	<input type="text" value="5"/> mm
Left rear	<input type="text" value="6"/> mm
Right rear	<input type="text" value="6"/> mm
Spare	<input type="text" value="Yes"/>
Tools	<input checked="" type="checkbox"/>

Interior	
AC Operation	<input checked="" type="checkbox"/>
Heater fan	<input checked="" type="checkbox"/>
Seatbelts	<input checked="" type="checkbox"/>
Horn	<input checked="" type="checkbox"/>

Turners Certified Key
 = Pass = Fail
 = Not applicable for this vehicle

Inspected by: Daryll Timms Date: 01 Feb 2019

I have read and understood this condition guide. Name: Signature: