

Report ID: 17,671,873 Version: 1 05 Feb 2019 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2011	Registration:		Reg Expiry:	28 Feb 2019	Engine	1 435	1 011	
	06 Jun 2019	Odometer:	185,720 Kms	Good No:	17671873	Oil level	~		
VIN:	MR0EZ12G704011082			Service Histor		Smoke & fumes			
	MR0E212G704011082	Next Service.	unknown	Service mistor	<b>y.</b> NO		~		
	port is not a warranty					Performance	~		
This report is	a guide only. Conside	eration is made	for age and mileage	e. Parts have not	been dismantled or	Noise	~		
	ical inspection prior to					Cooling System			1
						Coolant condition	~		
Key:	S D W		S P SC W		S D SC	Performance	~		
S = scratch	~	(0)		(O)	$\checkmark$	Radiator / Hoses (visual)	~		
D = dent					AD SD	Transmission		1	-
R = rust	s sc				HILL	Operation	~		
PT = paint def	ect NM				P SC	Noise	~		
C = crack					P SC	Clutch	~		
P = pin dent	PSC de				24H5	CV joints			~
* = decals		10		10	SD SD	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	P W W	C	S P S P S C		S D SC	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Number plate lights not working.						Tyres (lowest observed tread depth of tyres)			es)
L/H roof moulding missing.						Left front 6 mi			mm
Plastic steps missing off rear bumper. Detachable tow bar.						Right front		7	mm
Stone chipped screen.						Left rear		5	mm
Condition	as During Pody Inc	action				Right rear		5	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
OK, dirty.		•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
							V		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
rins holes & very dirty						Electrical / Accessories			
Seats						Head lights	~		
Carpets	very dirty.					Tail lights	~		
	door fabrie	damaged. all pa	anals yony dirty			Indicators	~		
Panels		. uamayeu, an pa	aneis very unity.			Dashboard warning lights	~		
Dashboa	rd cup holder	r faces missing, g	love box catch broker	n.		Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Heater fan not working on hi. Untidy but OK.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	1	•	•
Road Conditions During Test Drive: Dry Central locking									
			•			Remote locking	~		
Engine Ti	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 15	1,272	Reversing camera			~
						_	1	1	1
Inspected by: Daryll Timms Date: 05 Feb 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....