

Basic Vehicle Condition Guide

Report ID: 17,672,190


Version: 3

Created: 21 Feb 2019

Make: Model: Nissan Murano **Body Style:** SUV Year: 2010 Registration: FHE788 Reg Expiry: 22 Sep 2019 WoF Expiry: **Odometer: Good No:** 17 Dec 2019 129,463 Kms 17672190 VIN: JN1TANZ51A0003491 Next Service: 137053 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Detachable tow bar.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

OK.

| Interior Comments | | | |
|-------------------|----------------------------------|--|--|
| Seats | front seat rear pockets damaged. | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Good | | |

General Comments

Good AWD SUV.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Daryll Timms Inspected by: Date: 07 Feb 2019

| | Pass | Fail | N/A |
|---|--|----------|----------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | <i>v v</i> | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed treac | l depth | of tyre | ! !s) |
| Left front | | .0 | mm |
| Right front | 5.0 | | mm |
| Left rear | 3.0 | | mm |
| Right rear | | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | V V V | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | | | |
| Window winder RR | \(\sigma \) | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | <u> </u> | I |
| Central locking | ~ | | |
| Remote locking | | | |
| | <i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i> | | ı |
| Sat. Nav. (basic test only) | • | | ~ |
| Sat. Nav. (basic test only) Reversing camera | V | | ~ |

I have read and understood this condition guide.

Name:

Signature: