

Report ID: 17,673,761

Version: 1


14 Feb 2019 Created:

N/A

1

mm $\mathsf{m}\mathsf{m}$ mm

 $\mathsf{m}\mathsf{m}$



Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Murray Craig

Inspected by:

Evidence of Cam Belt Replacement: No

I have read and understood this condition guide.

	Remote locking	~									
	Sat. Nav. (basic test only)	~									
Kms:	Reversing camera	~									
Date: 14 Feb 2019											
Name:	Signature:	••••••	••••••								

Number of keys Central locking

Make:	Land Rover	Model:	Range Rover	Body Style:	Wagon			Pass	Fail	1
Year:	2017	Registration:	KKQ74	Reg Expiry:	09 Mar 2019		Engine			
WoF Expiry:	10 Mar 2020	Odometer:	15,994 Kms	Good No:	17673761		Oil level	~		
VIN:	SALVA2AD3GH112800	Next Service:	23,000	Service Histor	r y: No		Smoke & fumes	~		
							Performance	~		
	port is not a warranty s a guide only. Conside	eration is made	for age and mileage	. Parts have not	t been dismantled or		Noise	~		
diagnostic te	sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends		Cooling System			
a full mechar	nical inspection prior to	purchase and t	nis can be arranged fo	or an additional	cnarge.		Coolant condition	~		
			S SC			1	Performance	~		
Key: S = scratch		$=$ $\langle O \rangle$	7	Z(Q);=			Radiator / Hoses (visual)	~		
5 = scratch D = dent	NE				AD	_	Transmission			
R = rust						J	Operation	~		
PT = paint def	ect NP					_	Noise	~		
C = crack						J	Clutch			,
P = pin dent	HIP				24HF		CV joints	~		
* = decals	- Alk			7			Wheel bearings	~		
SC = stone chips W = significant scuffs					Brakes					
vv – sigrillicari	it scurs		PW				Performance	~		
Rody Insi	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram		Hand Brake	~		
	neel flare broken clips	•					Tyres (lowest observed tread	depth	of tyre	es)
2,	ree mare pronen emps						Left front	6	5	m
							Right front	ϵ	5	m
						╛	Left rear	7	7	m
Conditio	ns During Body Ins	pection:	Dry			1	Right rear	7	7	m
	3					=	Spare		Yes	
<u>Under Ca</u>	arriage & Under Bor	nnet Inspectio	on Comments				Suspension			_
							Suspension performance	~		
							Steering performance	~		
							Shock absorbers	~		
							Air Conditioning / Heater			
						=	Operation	'		
Interior C	<u>Comments</u>						Electrical / Accessories			<u></u>
Seats	Good						Head lights	'		
	Good						Tail lights	~		
Carpets	Good						Indicators	~		
Panels	Good						Dashboard warning lights	~		
	Good						Wipers (front & rear)	~		
Dashboa	ard Good						Window winder FL	~		
-	<u>'</u>					_	Window winder FR	~		
General (<u>Comments</u>						Window winder RL	~		Г
							Window winder RR	~		T
							Rear view mirrors	~		
							Radio (basic test only)	~		F
							CD (basic test only)	~		
							•			_