

Report ID: 17,689,362 Version: 2 24 Sep 2019 Created:

Make:	Toyota	Model:	Yaris	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2014	Registration:	HQS939	Reg Expiry:	29 Sep 2019	Engine			
WoF Expiry:	28 Aug 2020	Odometer:	31,356 Kms	Good No:	17689362	Oil level	~		
VIN:	JTDKW3D320D558051	Next Service:	45,000kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	lis can be arranged to	r an additional C	narge.	Coolant condition	~		
	SC W		SD SP		P SC	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s sc			10	HI SD	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack				The second secon		Clutch			~
P = pin dent	sc de				2416	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
in significant	SC S	C	S P SC	S	Р	Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
R/H wing mirror casing scratched.						Tyres (lowest observed tread depth of tyres)			
						Left front	e	5	mm
						Right front	e	5	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Wet Right rear							4.	.5	mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
OK.						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
Air C						Air Conditioning / Heater			
Operation Operation							~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General Comments Nice little hatch.						Window winder RL	~		
	מנכוו.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Conditions During Test Drive: Dry							~		
Engine Timing Mechanism: Timing Chain							~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Beversing camera									~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Daryll Timms Date: 24 Sep 2019									

I have read and understood this condition guide.

Name:

Signature: