

Basic Vehicle Condition Guide

Report ID: 17,689,888


Version: 3

Created: 14 Aug 2019

Make: Model: Hyundai Getz **Body Style:** Hatchback Year: 2008 Registration: ELW112 Reg Expiry: 27 Oct 2019 WoF Expiry: **Odometer:** 17 Aug 2020 179,084 Kms **Good No:** 17689888 VIN: KMHBT51DR8U80557 Next Service: 183,000kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

L/R panel seam split.

Wing mirror casings scratched, r/h casing broken.

Aerial missing.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Dirty,

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	drivers door handle chrome peeling.		
Dashboard	steering wheel perishing.		

General Comments

Nice manual hatch.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 100,000

Inspected by: Daryll Timms Date: 08 Aug 2019

Cleate	u. 1-	Trug 2	2017
	Pass	Fail	N/A
Engine	•	•	•
Oil level	~		
Smoke & fumes	~		
Performance	V		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission	ı		1
Operation	~		
Noise	~		
Clutch	\(\times \)		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	 ≥s)
Left front			mm
Right front	5.0		mm
Left rear	5.0		mm
Right rear	6.0		mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	<i>y</i>		
Shock absorbers	~		
Air Conditioning / Heater	_		
Operation	V		
Electrical / Accessories			
Head lights	./		
Tail lights	~		
Indicators			
Dashboard warning lights	ン ン		
Wipers (front & rear)	~		
Window winder FL			
Window winder FR	V		
Window winder FR Window winder RL	•		
	✓ ✓		
Window winder RR			
Rear view mirrors	•		
Radio (basic test only)	•		
CD (basic test only)	~		
Number of keys	3		
Central locking	'		
Remote locking	'		
Sat. Nav. (basic test only) Reversing camera			~

I have read and understood this condition guide.

Name:

Signature: