



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	17,690,379
Version:	1
Created:	19 Sep 2019

Make:	Volkswagen	Body Style:	Hatchback
Model:	Polo	VIN:	WVWZZZ9NZ8U004545
Year:	2008	Odometer:	32,773 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good	<div>Turners Certification Key:</div> <div>✓ = Pass</div> <div>✗ = Fail</div> <div>• = Not applicable for this vehicle</div>																										
1	Battery	✓	31	Reversing Camera	•	55	Coolant Condition	✓	79		Sun Roof Operation	•																								
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80		Front Windscreen (no chips)	Good																								
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81		Back Windscreen (no chips)	Good																								
4	High Stop Light	✓	Transmission and Drive		Suspension		58	Suspension Performance	✓		82	Side Windows (no chips)	Good																							
5	Front Right Indicators	✓	34	Operation	✓	59	Steering Performance	✓	83		Front Wiper Blades	Good																								
6	Front Left Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	84		Rear Wiper Blade	Good																								
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front		6	mm	85	R/H Mirror	Good																					
8	Rear Left Indicators	✓	37	CV Joints	✓	62	Right Front	6	mm		63	Left Rear	6	mm	86	L/H Mirror	Good																			
9	Reversing Lights	✓	38	Wheel Bearing	✓	64	Right Rear	6	mm		65	Spare	Yes	66	Tools	✓	87	L/F Guard	Good																	
10	Rear Reflectors	✓	39	Wheel Balance	✓	65	Spare	Yes	66	Tools	✓	88	R/F Guard	Good																						
11	Hazard Lights	✓	40	Gearbox (Manual)	•	Interior		67	AC Operation	✓	89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good																	
12	Courtesy Lights	✓	41	Engine Timing	Cambelt	68	Heater Fan	✓	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good																
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	No	69	Seatbelts	✓	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓																
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		70	Horn	✓	71	Seat Heaters	•	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good							
15	Number Plate Light	✓	Brakes		Interior		67	AC Operation	✓	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	68	Heater Fan	✓	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓	
17	Speedo	✓	45	Rear Brakes	✓	69	Seatbelts	✓	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓	
18	Odometer	✓	46	Handbrake	✓	70	Horn	✓	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓	
19	Rev Counter	✓	Keys and Locking		70	Horn	✓	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓		
20	Fuel Gauge	✓	47	Central Locking	✓	71	Seat Heaters	•	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓	
21	Wipers Front/Rear	✓	48	Remote Locking	✓	72	Sun Visors	✓	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓	
22	Window Opener FL	✓	49	Number of Keys	2	73	Sun Visors Lights/Mirrors	✓	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓	
23	Window Opener FR	✓	Engine		74	Seats	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓		
24	Window Opener RL	✓	50	Oil Level	✓	75	Carpets	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓	
25	Window Opener RR	✓	51	Smokes and Fumes	✓	76	Panels	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓	
26	Rear View Mirrors	✓	52	Performance	✓	77	Dashboard	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓	
27	Radio (Basic Test Only)	✓	53	Noise	✓				92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓	
28	CD (Basic Test Only)	✓	54	Starter Motor	✓				92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓	
29	Boot Open Switch	✓							92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓	

## Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Daryll Timms	Date:	19 Sep 2019
---------------	--------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--