

## **Basic Vehicle Condition Guide**

Report ID: 17,690,875


Version: 2

Created: 12 Sep 2019

Make: Model: Mazda Mazda3 **Body Style:** Hatchback Year: 2011 Registration: FSR459 Reg Expiry: 20 Oct 2019 WoF Expiry: **Odometer:** 19 Aug 2020 272,530 Kms **Good No:** 17690875 VIN: JM0BL10F100199359 **Next Service:** 284,000kms **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Conditions During Body Inspection:** Dry

OK.

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments		
Seats	pocket ripped on back of front passenger seat.	
Carpets	Average	
Panels	cargo shelf missing.	
Dashboard	Average	

## **General Comments**

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

**Daryll Timms** 14 Aug 2019 Inspected by: Date:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
	•	
~		
~		
depth	of tyre	es)
5.0		mm
Yes		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
1		
~		
~		
		~
		~
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	

I have read and understood this condition guide.

Name: .....

Signature: .....