

Report ID: 17,691,220 Version: 4 Created: 07 Aug 2020

Make:	Mini	Model:	Mini	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2004	Registration:	EPL188	Reg Expiry:	22 Jul 2020	Engine	1 4 3 3	1 011	
WoF Expiry:		Odometer:		Good No:	22 Jul 2020 17691220	Oil level			
VIN:	WMWRC32060TG3738		233,870 Kms	Service Histor		Smoke & fumes	~		
VIIN.	WWWRC320601G3738	Next Service:	243874	Service Histor	y: No		~		
Note: This re	port is not a warranty					Performance	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or disapactic tacting undertaken. The webicle has been driven up to 50km/h from cold. The Vender recommends							~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		<u> </u>
Key:	SC		S		S	Performance	~		ļ
S = scratch						Radiator / Hoses (visual)			
D = dent						Transmission			
R = rust					HIV	Operation	~		
PT = paint defe	ect N					Noise	~		
C = crack						Clutch		~	
P = pin dent						CV joints	~		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
	SC	\mathcal{O}	S			Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
Bonnet struts fail						Tyres (lowest observed tread depth of tyres)			
Key very poor						Left front	5.1 m		mm
						Right front	6	.1	mm
						Left rear	1	.9	mm
Conditions During Body Inspection: Dry						Right rear			mm
Conditions During Body inspection. Dry						Spare	No		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty						Suspension performance	~		
Oil leak						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		1
Interior Comments						Electrical / Accessories			
Conto	Average					Head lights			1
Seats							~		-
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
Ganaral	omments					Window winder FR	~		
General Comments clutch needs replaced						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry							~		
	-		•			Remote locking		~	
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Stuart Melbourne Date: 23 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: