

Note: some defects & blemishes may not be displayed in the diagram

Under Carriage	& Under	Bonnet l	nspection	Comments
enaci cannage	a onider	Donneen	nopeedon	commentes

Dry

Two tonneau ties broken. Right inner sill needs painting.

W = significant scuffs

D

Conditions During Body Inspection:

Body Inspection Comments

			Steering performance	~		
			Shock absorbers	~		
			Air Conditioning / Heater			
			Operation	~		
Interior Comments			Electrical / Accessories			
Seats	Average		Head lights	~		
Carpets	Average		Tail lights	~		
Carpets			Indicators	~		
Panels Good			Dashboard warning lights	~		
Good			Wipers (front & rear)	~		
Dashboard			Window winder FL	~		
			Window winder FR	~		
<u>General Comments</u>			Window winder RL	~		
			Window winder RR	~		
			Rear view mirrors	~		
			Radio (basic test only)	~		
			CD (basic test only)	~		
			Number of keys	2	•	
Road Conditions During Test Drive: Dry			Central locking	~		
·			Remote locking	~		
Engine Timing Mechanism: Timing Chain			Sat. Nav. (basic test only)		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:			Reversing camera		~	
Inspected by:	Brian Hill		Date: 20 Aug 20	19		

I have read and understood this condition guide.

Name:

2

Pass

V

V

V

V

V

V

V

V

V

V

V

~

~

5

5

4

2

V

Yes

Tyres (lowest observed tread depth of tyres)

Brakes

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance

Spare

20 Aug 2019

Fail

N/A

V

mm

mm

mm

mm