

Report ID: 17,691,824 Version: 3 03 Sep 2019 Created:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2002	Registration:	FCL222	Reg Expiry:	14 Oct 2019	Engine	1		L
WoF Expiry:	10 Sep 2020	Odometer:	131,975 Kms	Good No:	17691824	Oil level	~		
VIN:	7A8GK0C0709713299	Next Service:	142000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									<u> </u>
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
	P SC W		S SC SC		SC	Performance	~		
Key:	PSC W	-0	s sc sc	$- \square$		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	sc			715	HIV	Operation	~		
PT = paint defe		F I		$\left[\left(\right) \right]$		Noise	~		
C = crack					Р	Clutch			~
P = pin dent	HIP				7414	CV joints	~		
* = decals	PSC 916			The second	ALD S	Wheel bearings	~		
SC = stone chips						Brakes			L
W = significan	t scuffs W		PT SC PT		SC	Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	l depth	of tyre	<u>)</u> 25)
Chipped screen.									mm
						Right front	6		mm
						Left rear	4		mm
Conditions During Body Inspection: Dry Right rear							4.0 mm		mm
Conditions During Body inspection. Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy.						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
Air Col									I
Oper						Operation	 ✓ 		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Avelage					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Card					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	1					Window winder FR	~		
General Comments Window winder RL							~		
Tidy little hatch. Key remote not working.						Window winder RR	~		
Key remote	not working.					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
Number of keys							1		
			Dry			Remote locking	~	~	
Engine Tir	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)		-	~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Daryll Timms Date: 19 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: