

Pass Fail N/A

| Year: | 2014 | Registration: | HFQ401 | Reg Expiry: | 21 Oct 2019 | | Engine | | | | |
|--|--|----------------------|---------------------|--------------------|--------------------|----|---|-------|---|----------|--|
| WoF Expiry: | 22 Jan 2020 | Odometer: | 71,752 Kms | Good No: | 17692958 | | Oil level | ~ | | | |
| VIN: | WF0YXXTTGYDK8250 | Next Service: | 97400 | Service Histor | y: Yes | | Smoke & fumes | ~ | | | |
| | | | | | | | Performance | ~ | | | |
| | port is not a warranty a quide only Conside | eration is made | for age and mileage | Parts have not | been dismantled or | | Noise | ~ | | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | | Cooling System | | | | |
| | | | | | | | Coolant condition | ~ | | | |
| | | | C C | | | ٦ | Performance | ~ | | | |
| Key: | | -0 | | 500- | | | Radiator / Hoses (visual) | ~ | | | |
| S = scratch D = dent R = rust | | | | | | | Transmission | | | | |
| | | | | | | J | Operation | ~ | | | |
| PT = paint defe | ect NP | | | | 17111 | | Noise | ~ | | | |
| C = crack | | | | | | 1 | Clutch | ~ | | | |
| P = pin dent | | | | | | | CV joints | ~ | | | |
| *=decals | | | | | | | Wheel bearings | ~ | | | |
| SC = stone chips | | | | | | | Brakes | | | | |
| W = significant scuffs W S S | | | | | | | Performance | ~ | | | |
| Rody Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | | Hand Brake 🖌 | | | | |
| Body Inspection Comments | | | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| | | | | | | | Left front | 5 mm | | mm | |
| | | | | | | | Right front | 3. | 5 | mm | |
| | | | | | | | Left rear | 8. | 5 | mm | |
| Conditions During Body Inspection: | | | | | | | Right rear | 8.5 m | | mm | |
| | | | | | | | Spare Yes | | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | | Suspension | | | | |
| Tidy | | | | | | | Suspension performance | ~ | | | |
| | | | | | | | Steering performance | ~ | | | |
| | | | | | | | Shock absorbers | ~ | | | |
| | | | | | | | Air Conditioning / Heater | | | | |
| | | | | | | | Operation 🖌 | | | | |
| Interior Comments | | | | | | | Electrical / Accessories | | | 1 | |
| Seats | Good | | | | | | Head lights | ~ | | | |
| | Good | | | | | | Tail lights | ~ | | | |
| Carpets | 0000 | | | | | | Indicators | ~ | | | |
| Panels | Good | | | | | | Dashboard warning lights | ~ | | | |
| | , Good | | | | | | Wipers (front & rear) | ~ | | 1 | |
| Dashboa | rd | | | | | | Window winder FL | ~ | | <u> </u> | |
| | 1 | | | | | ┤╎ | Window winder FR | ~ | | | |
| General Comments | | | | | | | Window winder RL | | | ~ | |
| | | | | | | | Window winder RR | | | ~ | |
| | | | | | | | Rear view mirrors | ~ | | | |
| | | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | | CD (basic test only) | ~ | | | |
| | | | | | |][| Number of keys | 2 | | 1 | |
| Road Conditions During Test Drive: Dry | | | | | | ןך | Central locking | ~ | | | |
| | - | | • | | | ╵└ | Remote locking | ~ | | | |
| Engine Timing Mechanism: Cambelt | | | | | | | Sat. Nav. (basic test only) | | | ~ | |
| Evidence | of Cam Belt Replac | ement: N | lo | Kms: | | | Reversing camera | | | ~ | |
| | | | | | | | - | | | | |
| Inspected by: Stuart Melbourne Date: 03 Sep 2019 | | | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: