

Report ID: 17,693,026 Version: 1 02 Sep 2019 Created:

Make:	Honda	Model:	Accord	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2009	Registration:	EWS921	Reg Expiry:	29 Jul 2019	Engine			L	
WoF Expiry:	10 Jul 2020	Odometer:	247,828 Kms	Good No:	17693026	Oil level	~			
VIN:	JHMCU26409C212040	Next Service:	250428	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~			
	S D W		SC	W	S	Performance	~			
Key:		$-\infty$		-(M-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust	SC DE			715	HIL	Operation	~			
PT = paint defe		F		$\left(\left \left(\right) \right\rangle \right)$		Noise	~			
C = crack				+	SC	Clutch			~	
P = pin dent	HIC				74114	CV joints	~		-	
* = decals	sc 916			-No-	ELE PT	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SC W S D						Performance	~			
		Note: son	ne defects & blemishes	s may not be disc	blaved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	of tyre	L	
Stone chips front screen						Left front 3 mm				
						Right front		, }	 mm	
						Left rear			mm	
Conditions Duving Pody/Inspections						Right rear			mm	
Conditions During Body Inspection: Wet						Spare	4 mm Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
		•				Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	v		<u> </u>	
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats Good										
Seals						Tail lights	~			
Carpets	Good					Indicators	~			
	Good						~			
Panels						Dashboard warning lights Wipers (front & rear)	v			
Dashboa	rd Good					Wipers (front & rear) Window winder FL	v			
						Window winder FL Window winder FR	~			
General C	Comments						v			
						Window winder RL	v			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	/		L	
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
Engine Timing Mechanism: Timing Chain						Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
	or cam beit neplac			11113.		Reversing camera			~	
Inspected by: Brian Hill Date: 02 Sep 2019										

I have read and understood this condition guide.

Name:

Signature: